



DRY TRANSFER DECALS

- Cut out desired Decal, leaving a slight edge. Apply to a dry, dust-free surface.
- Hold Decal firmly in place. Rub entire back of Decal gently with a burnisher or dull pencil.
- Lift carrier sheet slowly. If transfer was not complete, let carrier sheet fall back in place and reburnish.
- Place backing paper over Decal and reburnish.



- S'appliquent à sec, sans poussière surface. Découper souhaité vignette, laissant un léger avantage.
- Tenir vignette fermement en place. Frotter toute retour de vignette doucement avec un monobrosse ultra haute vitesse ou terne utilisant un crayon.
- Ascenseur transporteur feuille lentement. Si des transferts n'était pas complète, laissez transporteur feuille retomber en place et reburnish.
- Lieu papier protecteur de vignette et reburnish.



TIP!

- For maximum durability, apply a very light coat of gloss.

NOTE: Test gloss on a small area before applying to entire racer.

- Cut racing stripes shorter or place end-to-end for longer sections.

ASTUCE!

- Pour maximum de durabilité, s'appliquer une très légère couche de brillant.

NOTE: L'essai brillant sur une petite zone avant d'appliquer à l'ensemble coureur.

- Couper coureur raie plus courtes ou lieu fin-fin pour plus sections.

CAUTION: Cutting tool recommended. Use with care.

Conforms to Health Requirements of ASTM D4236

E7 ©2003 O CO